

Conversion of machines with MAC-Servomotors

The Bosch-Rexroth MAC-motor-generation has already been discontinued some time ago and repairs are often no longer possible due to a lack of spare parts availability. Since we now have no more overhauled MAC motors in stock, we would like to offer our customers an alternative to avoid machine downtimes and to ensure continued operation. We offer the retrofitting to MSK-motors with IndraDrive controllers.


Your benefits

- | Spare parts availability is guaranteed again
- | Avoidance of machine stops
- | Reliability is enhanced

Available for machines

some examples:

RV 53 to #652		RV 74 to #183
RDK 54 to #156		RDK 54 #158 to #163
RDK 54c		RDK 54d
RDKP 72		RDKP 72d
RDKP 72e		RDKP 72g to #659
RDK 80 to #658		more on request



MAC - motor generation